

## Bayliner 242 Classic

Type:	<b>Motorboat</b>
Year built:	2005
Material:	Fiberglass
Motorization:	1x Mercruiser (220 PS)
Milage:	10 h
Transmission:	
Speed:	No description
Max. speed:	No description
Length:	7,32 m (24,0 ft.)
Width:	2,44 m (8,0 ft.)
Draft:	0,91 m (3,0 ft.)
Weight:	No description
Fuel tank:	81 L
Water tank:	No description
Cabins:	1
Beds:	No description
Bathrooms:	No description
Anchored at:	Suffolk County, NY
Price:	<b>21.128 GBP</b> VAT not paid



### Description:

You can own this vessel for as little as \$309 per month. Visit the POP Yachts website for more information.

### Manufacturer Discription;

With a bright, spacious cabin, comfortable sleeping quarters, a well-equipped galley and a private head, each Bayliner Cruiser boasts all the key amenities for restful overnighting. Daytime onboard is equally blissful, with a roomy cockpit and foredeck. Bayliner Cruisers offer generous power and storage capacity, too, all while remaining affordable. There's no end to how far or how long you can cruise, so feel free to go ahead and chase the horizon.

Please submit any and ALL offers - your offer may be accepted! Submit your offer today!

We encourage all buyers to schedule a survey for an independent analysis. Any offer to purchase is ALWAYS subject to satisfactory survey results.

Take a look at ALL \*\*\*83 PICTURES\*\*\* of this vessel on our main website at POPYACHTS DOT COM. Contact us for a free BoatHistoryReport.com report on this vessel. We pay upfront for a report on every vessel possible, and we provide this peace of mind to our buyers at no charge and with no commitment. All you have to do is ask! At POP Yachts, we will always provide you with a TRUE REPRESENTATION of every vessel we market. We are a full-service brokerage company, ready to assist you in purchasing any boat anywhere! Please allow us to be your eyes and ears on the ground and assist you with your next vessel purchase. Thank you for visiting and we look forward to speaking with you!

- Stock #17711 Boat has been stored for a few years. Motor replaced by factory, only 10 hours on new motor. Damage to swim platform. Outside of boat & deck is extremely dirty. Inside cabin looks in good condition.



Outside view - Image 1